

***ViewPowerPro Change Log (Version 2.0-25210):**

1. Fixed a command injection vulnerability.
2. Strengthened access control for configuration operations: Added two-factor authentication (2FA) to prevent unauthorized users from manipulating the UPS.
3. Implemented a login failure limit policy: Multiple failed login attempts will trigger a 10-minute account lockout, effectively mitigating brute force and DoS attacks.
4. Fixed a remote code execution (RCE) vulnerability triggered by the Content-Type HTTP header.
5. Fixed a Java RMI Registry local host bypass enumeration vulnerability.
6. Strengthened clickjacking protection: Prevented pages from being embedded in malicious frames by setting the X-Frame-Options: DENY response header.
7. Enhanced database security: Encrypted stored database credentials.
8. Upgraded the Java runtime environment to JDK 17.0.4.
9. Updated multiple third-party dependencies to the latest secure/stable versions.